

UDC 621.43.001.2

Mishchenko N.I., Zarenbin V.G., Kolesnicova T.N.,

Suprun V.L. Errors of elements in non connecting rod engine with crank-link mechanism // Internal combustion engines. – 2005. – 1. – P. 86-89.

The errors arising at manufacturing and installation of elements in non connecting rod engine are considered.

Parities for definition of angular fluctuations of a side scene and radial moving of the piston are produced, the errors caused by action are resulted. II. 4. Bibliogr. 2 names.